

Site Inspection Report for Charlotte County – Ann & Chuck Dever Regional Park & Community Pool Splash Pad Florida Hurricane Ian (DR-4673-FL)







Created: 8/2/2023, 9/2/2023 (FEMA), 10/16/2023 (FEMA),


12/4/2024 (Splash Pad Initial), 1/11/2024 (FEMA)

**Location:** Ann & Chuck Dever Regional Park

Address: 6791 San Casa Drive, Englewood, Florida, 34224

No. Items:

(1)



Created: Mon 16 Oct 10:41 2023

Group: Skateboard Park Shade & Structure A

Company: CSA Consulting Group

GPS Lat/Lon: 26.92021, -82.31411 Cause of Damage: High Winds

**Component Description:** 

Overview Photo of Shade Structure

Shade Structure (20' x 25')

- (4) 12' Posts (above grade)
- (4) Rail Beams
- (2) Sleeve(s)
- Approximate shade dimensions 25' L x 20' W



Created: Mon 16 Oct 10:41 2023

**Group:** Playground Picnic Shade & Structure B

**GPS Lat/Lon:** 26.91977, -82.31475 **Cause of Damage:** High Winds

**Component Description:** 

Overview Photo of Shade Structure (1)

Approximately 400 SF of BCI Burke® ShadePlay Canopy Square shaped fabric,

Approximate shade dimensions 20' L x 20' W

4 each of BCI Burke® Play Systems Galvanized steel tube posts and associated footings, Approximately 14 FT long x 8 IN in diameter

4 each of BCI Burke® Play Systems Galvanized steel tube top shade connector arms, Approximately 13 FT long x 5 IN in diameter Created: 8/2/2023, 9/2/2023 (FEMA), 10/16/2023 (FEMA),

12/4/2024 (Splash Pad Initial), 1/11/2024 (FEMA)

**Location:** Ann & Chuck Dever Regional Park

Address: 6791 San Casa Drive, Englewood, Florida, 34224

No. Items:

(3)



Created: Mon 16 Oct 10:41 2023

Group: Playground Picnic Shade & Structure B

Company: CSA Consulting Group

GPS Lat/Lon: 26.91977, -82.31475 Cause of Damage: High Winds

**Component Description:** 

Approximately 400 SF of BCI Burke® ShadePlay Canopy Square shaped fabric,

Approximate shade dimensions 20' L x 20' W

4 each of BCI Burke® Play Systems Galvanized steel tube posts and associated footings, Approximately 14 FT long x 8 IN in diameter

4 each of BCI Burke® Play Systems Galvanized steel tube top shade connector arms, Approximately 13 FT long x 5 IN in diameter



**Created:** Mon 16 Oct 10:41 2023

**Group:** Playground Picnic Shade & Structure B

**GPS Lat/Lon:** 26.91977, -82.31475 **Cause of Damage:** High Winds

**Component Description:** 

Approximately 400 SF of BCI Burke® ShadePlay Canopy Square shaped fabric,

Approximate shade dimensions 20' L x 20' W

4 each of BCI Burke® Play Systems Galvanized steel tube posts and associated footings, Approximately 14 FT long x 8 IN in diameter

4 each of BCI Burke® Play Systems Galvanized steel tube top shade connector arms, Approximately 13 FT long x 5 IN in diameter **CSA** 

**Created:** 8/2/2023, 9/2/2023 (FEMA), 10/16/2023 (FEMA),


12/4/2024 (Splash Pad Initial), 1/11/2024 (FEMA)

**Location:** Ann & Chuck Dever Regional Park

Address: 6791 San Casa Drive, Englewood, Florida, 34224

No. Items:

(5)



Created: Mon 16 Oct 10:41 2013

**Group:** Umbrella Shade and Structure C

GPS Lat/Lon: 26.91968, -82.31470 Cause of Damage: High Winds

**Component Description:** 

225 SF of BCI Burke® ShadePlay Umbrella Shade approximate shade dimension 15 FT long x 15 FT wide


Company: CSA Consulting Group



Site Inspection Report for Charlotte County – Carmalita Park Florida Hurricane Ian (DR-4673-FL)







Mon 02 Oct 16:03 2023 Created:

Location: Carmalita Park

Title: 2605 Carmalita St, Punta Gorda, Florida

33950

No. Items: 8

Contact:

**Company:** CSA Consulting Group

**Created:** Tue 03 Oct

15:10 2023

Group: Signage

Cause of Damage: N/A

**GPS Lat/Long:** 26.92950,

-82.01940

**Component Description:** 

Overview Photo of Park Entry Signage



(2)





MegaSpan shade structure missing.

10" Diameter Posts - Center post

22' to top

Approximate shade dimensions 50' L x 50' W



**Created:** Mon 02 Oct 16:03 2023

**Location:** Carmalita Park Company: CSA Consulting Group

Contact:

Title: 2605 Carmalita St, Punta Gorda, Florida

No. Items: 8

(3)



Football Field Umbrella Shade

**Group:** and Structure A **Cause of Damage:** Wind/Wind-

Borne Debris

**GPS Lat/Long:** 26.93039, -82.02129

# **Component Description:**

Umbrella Shade(10). Structural damage at the arm. Shade missing. Bolts and nuts have stress bends.

Approximate shade dimensions 20' L x 20' W

(4)



Created: Tue 03 Oct

Football Field Umbrella Shade

Group: and Structure B

Cause of Damage: Wind/Wind-

**Borne Debris** 

**GPS Lat/Long:** 26.93065, -82.02134

# **Component Description:**

Sustain tensional bends at one arm.

Approximate shade dimensions 20' L x 20' W

5' x 5' x 5' concrete foundation under grade.

**Created:** Mon 02 Oct 16:03 2023

**Location:** Carmalita Park Company: CSA Consulting Group

Contact:

Title: 2605 Carmalita St, Punta Gorda, Florida

No. Items: 8

(5)



Football Field Umbrella Shade

**Group:** and Structure C **Cause of Damage:** Wind/Wind-

Borne Debris


**GPS Lat/Long:** 26.93129, -82.02122

# **Component Description:**

Stress bend at East Arm. (5) bent bolts.

Approximate shade dimensions 20' L x 20' W

(6)



Created: Tue 03 Oct

Football Field Umbrella Shade

**Group:** and Structure D

Cause of Damage: Wind/Wind-

**Borne Debris** 

**GPS Lat/Long:** 26.93107, -82.021342

### **Component Description:**

Bent arm.

Approximate shade dimensions 20' L x 20' W

5' x 5' x 5' concrete foundation under grade.

Created: Mon 02 Oct 16:03 2023

Location: Carmalita Park

Title: 2605 Carmalita St, Punta Gorda, Florida


No. Items: 8

Contact:

Football Field Umbrella Shade Group: and Structure D **Cause of Damage:** Wind/Wind-

Borne Debris

**GPS Lat/Long:** 26.93107, -82.021342



Main support post bent.

Refer to photo (31).

Company: CSA Consulting Group

Approximate shade dimensions 20' L x 20' W



(8)



**Created:** Tue 03 Oct

13:55 2023

**Group:** Playground Picnic Area

Shade and Structure A

Wind/Wind-**Cause of Damage:** 

**Borne Debris** 

**GPS Lat/Long:** 26.92834, -82.02115

### **Component Description:**

Rectangular Shade

Approximate shade dimensions 22' L x 15' W

Angle sleeve

4" pipe from sleeve

Missing shade.




Site Inspection Report for
Charlotte County –
Centennial Park Campus
Florida Hurricane Ian (DR-4673-FL)

Centennial
Park

2023/09/13 07:53 AM 27:0133: N 32:1766: V







Port Charlotte, Florida, 33953

No. Items: (8) Subject Item(s)

Contact:

Company: CSA Consulting Group

(1.)



**Created:** Wed 13 Sep 09:57 2023

Group: Soccer Field Mega Span Shade & Structure A

(Super Dome Hip Shade)

**GPS Lat/Lon:** 27.00855, -82.17830 **Cause of Damage:** Wind/Wind-Borne

Debris

#### **Component Description:**

Approximate shade dimensions 35.5' L x 30' W

8" diameter steel pipe apparently did not experience any win driven damage or bends.

Missing (2) steel tensile cables, and the fabric was blue in colour.

(2.)



**Created:** Wed 13 Sep 10:01 2023

**Group:** Soccer Field Mega Span Shade & Structure A

**GPS Lat/Lon:** 27.00855, -82.17830

Cause of Damage: N/A Component Description:

Approximate shade dimensions 35.5' L x 30' W

8" diameter steel pipe apparently did not experience any win driven damage or bends.

Missing (2) steel tensile cables, and the fabric was blue in colour.




Port Charlotte, Florida, 33953

No. Items: (8) Subject Item(s)

Contact:

CSA Consulting Group

(3.)



**Created:** Wed 13 Sep 10:02 2023

Group: Soccer Field Mega Span Shade & Structure A

**GPS Lat/Lon:** 27.00855, -82.17830 **Cause of Damage:** Wind/Wind-Borne

Debris

**Component Description:** 

8" diameter steel pipe apparently did not experience any win driven damage or bends.

Missing (2) steel tensile cables, and the fabric was blue in colour.

(4.)



**Created:** Wed 13 Sep 10:05 2023

**Group:** Soccer Field Mega Span Shade & Structure A

**GPS Lat/Lon:** 27.00855, -82.17830 **Cause of Damage:** Wind/Wind-Borne

Debris

**Component Description:** 

8" diameter steel pipe apparently did not experience any win driven damage or bends.

Missing (2) steel tensile cables, and the fabric was blue in colour.

Port Charlotte, Florida, 33953

No. Items: (8) Subject Item(s)

Contact:

Company: CSA Consulting Group

(5.)



**Created:** Wed 13 Sep 10:02 2023

Group: Playground Mega Shade & Structure D

GPS Lat/Lon: 27.01396, -82.17404

Cause of Damage: Wind/Wind-Borne

Debris

**Component Description:** 

1 each of approximate shade dimensions 45 FT long x 23 FT wide

CoolNet Aquatic Blue fabric and cables for an R2345 Playground Shade, includes

hardware

(6.)



**Created:** Wed 13 Sep 10:05 2023

**Group:** Playground Single Post Shade & Structure A

**GPS Lat/Lon:** 27.01393, -82.17388

Cause of Damage: Wind/Wind-Borne

Debris

**Component Description:** 

1 each of approximate shade dimensions 15 FT x 15 FT

Offset single post pyramid with shade and hardware.



Port Charlotte, Florida, 33953

No. Items: (8) Subject Item(s)

Contact:

Company: CSA Consulting Group

(7.)



Created: Wed 13 Sep 10:02 2023

Group: Playground Offset Shade & Structure B

GPS Lat/Lon: 27.01378, -82.17403

Cause of Damage: Wind/Wind-Borne

Debris

#### **Component Description:**

2 each of approximate shade dimensions 15 FT x 15 FT  $\,$ 

Offset single post pyramid with shade and hardware.

(8.)



**Created:** Wed 13 Sep 10:05 2023

**Group:** Playground Offset Shade & Structure C

**GPS Lat/Lon:** 27.01378, -82.17403

Cause of Damage: Wind/Wind-Borne

Debris


#### **Component Description:**

2 each of approximate shade dimensions 15 FT  $\times$  15 FT

Offset single post pyramid with shade and hardware.



Site Inspection Report for Charlotte County – Deep Creek Park Florida Hurricane Ian (DR-4673-FL)







**ICSA** 

Created: Tue 07 Nov 08:16 2023

Location: 25555 Sandhill Blvd., Port Charlotte, FL 33983 Company: CSA Consulting Group

Title: Mid County-Deep Creek Park

No. Items: (4) Subject Photos

**Contact:** 

Phone: Email:

(1)



Created: Tue 07 Nov 08:19 2023 Group: Park Entry Signage (A) **GPS Lat/Lon:** 27.017104, -82.025652 **Cause of Damage:** High Winds

**Component Description:** 

Overview Photo of the Park Entry Signage

(2)



Tue 07 Nov 08:27 2023 Created:

Group: Playground Mega Shade & Structure (A)

27.01669, -82.02577 GPS Lat/Lon: High Winds Cause of Damage:

**Component Description:** 

Mega Span Shade Structure suffered a large wind event which separated its fabric shade during the high wind event of hurricane Ian.

Approximate shade dimensions 65' L x 30' W

Created: Tue 07 Nov 08:16 2023

Location: 25555 Sandhill Blvd., Port Charlotte, FL 33983 Company: CSA Consulting Group Title:

Mid County-Deep Creek Park

No. Items: (4) Subject Photos

**Contact:** 

Phone: Email:

(3)



Created: Tue 07 Nov 08:28 2023

Group: Playground Mega Shade & Structure (A)

GPS Lat/Lon: 27.01669, -82.02577 Cause of Damage: High Winds

**Component Description:** 

Dimensions: (4) 10' Dia. Powder Coated Steel Column, High Quality Finish, Welded flange (top), (4) 4' x 4' x 3' CIP Footer(s), #5 Rebar, (16)

1-inch Bolt, Nut, Washer(s)

Approximate shade dimensions 65' L x 30' W



Created: Tue 07 Nov 08:35 2023

Playground Mega Shade & Structure (A) Group:

GPS Lat/Lon: 27.01669, -82.02577 Cause of Damage: High Winds

**Component Description:** 

Photo depicts (1) nut & washer missing from high tension vibrational stresses during the event.


Refer to Photo (3).



Site Inspection Report for Charlotte County – Franz Ross Park Florida Hurricane Ian (DR-4673-FL)







CSA Created: Tue 24 Oct 08:15 2023 Company: CSA Consulting Group

Location: Franz Ross Park

Address: 19333 Quesada Ave., Port Charlotte, FL 33948

No. Items: 3

(1)

Created: Tue 24 Oct 08:24 2023

Group: Playground Shade Structure (A) GPS Lat/Lon: 27.00878, -82.12923

**Cause of Damage:** Wind

**Component Description:** 

(2)

Playground Mega Shade and Structure A. Approximate shade dimensions 35' L x 30' W 9" diameter columns. Missing shade tabric.



**Created:** Tue 24 Oct 08:26 2023

Group: Playground Mega Shade and Structure A

GPS Lat/Lon: 27.00878, -82.12923

**Cause of Damage:** Wind Component Description: Refer to Photo (1). CSA Created: Company: CSA Consulting Group Tue 24 Oct 08:15 2023

Franz Ross Park

Address: 19333 Quesada Ave., Port Charlotte, FL 33948

No. Items: 3

(3)



Created: Tue 24 Oct 08:28 2023

Group: Playground Mega Shade and Structure A

**GPS Lat/Lon:** 27.00875, -82.12923

Cause of Damage: Wind **Component Description:** 

Refer to Photo (1).



**CSA** 

(2)

Created: Thu 21 Sep 10:42 2023
Location: Harold Avenue Regional Park

**Address:** 23400 Harold Avenue,

Port Charlotte, FL 33980

No. Items: (4) Subject items

Contact:

Company: CSA Consulting Group



**Created:** Thu 21 Sep 11:14 2023

**Group:** Signage

**GPS Lat/Lon:** 26.013714, -82.061389

Cause of Damage: N/A Component Description:

Overview Photo.



**Created:** Thu 21 Sep 12:14 2023

**Group:** Baseball Field 4

Shade & Structure A

GPS Lat/Lon: 27.01454, -82.06127 Cause of Damage: High Winds

**Component Description:** 

4-column mega span shade structure

fabric missing.

Approximate shade dimensions 31' L x 27' W

5" wide columns.

**CSA** 

**Created:** Thu 21 Sep 10:42 2023

**Location:** Harold Avenue Regional Park **Address:** 23400 Harold Avenue,

Port Charlotte, FL 33980

No. Items: (4) Subject items

Contact:

Company: CSA Consulting Group

(3)



**Created:** Thu 21 Sep 12:19 2023 **Group:** Baseball Field 4

Shade & Structure A

**GPS Lat/Lon:** 27.01454, -82.06127 **Cause of Damage:** High Winds

**Component Description:** 

4-column mega span shade structure fabric missing.

5" wide columns.

(4)



Created: Thu 21 Sep 12:19 2023

**Group:** Tennis Court Playground Shade

and Structure A

**GPS Lat/Lon:** 27.01436, -85.05825 **Cause of Damage:** High Winds

**Component Description:** 

Shade Structure Missing Fabric.


(High density polyethylene with Ultra-Violent UV Stabilized),

Approximate shade dimensions 45' L x 30' W

1 each of Metal Pole for Playground Shade - 18 FT(H) x 8-inch diameter



Site Inspection Report for Charlotte County – Rotonda Park Florida Hurricane Ian (DR-4673-FL)







**Company:** CSA Consulting Group

Created: Fri 17 Nov 11:19 2023

West County-Rotonda Park
Location: 100 Rotonda Blvd E, Rotonda West,

FL 33947

No. Items: (5) Subject Photos

**Created:** Fri 17 Nov 11:40 2023

**Group:** Playground Shade and Structure (A)

GPS Lat/Lon: 26.89140, -82.26998 Cause of Damage: High Winds

and Windborne Debris

#### **Component Description:**

Overview of damaged rectangular Shade Structure (A) and Swing Set (A) from fallen tree/windborne debris. Complete displacement of Shade Structure, only (1) column remains.

Rectangular Shade Structure: (per POC) Approximate shade dimensions 40' L x 40' W

Height: 15' above grade

4 each of 4IN x 4IN square shaped Galvanized Steel Posts, 15

FT high

4 each of Galvanized Steel Tubular Hip Rail Arms, 26 FT long x 5 IN in diameter

1 each of Galvanized Steel Tubular Truss, 6 FT long x 5 IN in diameter

**Created:** Fri 17 Nov 11:44 2023

**Group:** Playground Shade and Structure (A)

**GPS Lat/Lon:** 26.89140, -82.26998 **Cause of Damage:** High Winds

**Component Description:** 

Overview of Playground (A), counter angle depicts

missing structure and shade fabric.





(2)

**Company:** CSA Consulting Group

Fri 17 Nov 11:19 2023 Created: Title: West County-Rotonda Park Location: 100 Rotonda Blvd E, Rotonda West,

FL 33947

No. Items: (5) Subject Photos

**Created:** Fri 17 Nov 11:47 2023



Group: Playground Shade and Structure A 26.89140, -82.26998 GPS Lat/Lon: Cause of Damage: High Winds

**Component Description:** 

Close-up of Playground (A) remaining column, photo depicts the column to be Off Center as seen.



Created: Fri 17 Nov 11:50 2023

Playground Shade and Structure B Group:

GPS Lat/Lon: 26.89125, -82.26994 Cause of Damage: **High Winds** 

**Component Description:** 

Overview of Playground (B), counter angle depicts missing structure and shade fabric.

Approximate shade dimensions 24' L x 24' W

4 each of Tubular Galvanized Steel Posts - 5IN diameter, 12 FT high

4 each of Galvanized Steel Tubular Rail Arms, 12 FT long x 5 IN in diameter

(3)

**Company:** CSA Consulting Group

Created: Fri 17 Nov 11:19 2023
West County-Rotonda Park
Location: 100 Rotonda Blvd E, Rotonda West,

FL 33947

No. Items: (5) Subject Photos

Photo Showing what the playground shade structures looked like before Ian:



 $\underline{https://www.charlottecountyfl.gov/departments/community-services/parks/all-parks/rotonda-community-park.stml}$ 



Site Inspection Report for Charlotte County – South County Regional Park Complex Florida Hurricane Ian (DR-4673-FL)







Created: Tue 12 Sep 07:30 2023 Location: South County Regional Park

Address: 670 Cooper St, Punta Gorda, Florida,

33950

No. Items: 13 Contact:

Company: CSA Consulting Group, LLC.

Phone: Email:





Created: Mon 18 Sep 2023

Group: Picnic Area Shade and Structure A

GPS Lat/Lon: 26.93264, -82.03697 Cause of Damage: Wind/Windborne


Debris

**Component Description:** 

High density polyethylene with ultraviolet (U.V.) Shade Canopies for

Umbrella Shade Structure.

Approximate shade dimensions 20' L x 20' W



Mon 18 Sep 2023 Created:

Group: Picnic Area Shade and Structure B

GPS Lat/Lon: 26.93264, -82.03697 Cause of Damage: Wind/Windborne

Debris

**Component Description:** 

High density polyethylene with ultraviolet (U.V.) Shade Canopies for Umbrella Shade Structure.

Approximate shade dimensions 20' L x 20' W

CSA Created: Tue 12 Sep 07:30 2023

Location: South County Regional Park

Address: 670 Cooper St, Punta Gorda, Florida,


33950

No. Items: 13

Contact:

Company: CSA Consulting Group, LLC.

Phone: Email:



Created: Mon 18 Sep 2023

**Group:** Picnic Area Shade and Structure C

GPS Lat/Lon: 26.93264, -82.03697 Cause of Damage: Wind/Windborne

Debris

# **Component Description:**

High density polyethylene with ultraviolet (U.V.) Shade Canopies for Umbrella Shade Structure. Umbrella Metal Pole Cap (4 Connectors).

Approximate shade dimensions 20' L x 20' W



Created: Mon 18 Sep 2023

**Group:** Picnic Area Shade and Structure C

GPS Lat/Lon: 26.93264, -82.03697 Cause of Damage: Wind/Windborne

Debris

## **Component Description:**

High density polyethylene with ultraviolet (U.V.) Shade Canopies for Umbrella Shade Structure.

Approximate shade dimensions 20' L x 20' W

**CSA** Created: Tue 12 Sep 07:30 2023 South County Regional Park

Address: 670 Cooper St, Punta Gorda, Florida,


33950

No. Items: 13

Contact:

Company: CSA Consulting Group, LLC.

Phone: Email:



Created: Mon 18 Sep 2023

**Group:** Picnic Area Shade and Structure D

GPS Lat/Lon: 26.93264, -82.03697 Cause of Damage: Wind/Windborne


Debris

**Component Description:** 

High density polyethylene with ultraviolet (U.V.) Shade Canopies for Umbrella Shade Structure. Umbrella Metal

Pole Supports.

Approximate shade dimensions 20' L x 20' W



Created: Mon 18 Sep 2023

**Group:** Picnic Area Shade and Structure D

GPS Lat/Lon: 26.93264, -82.03697 Cause of Damage: Wind/Windborne

Debris

**Component Description:** 

High density polyethylene with ultraviolet (U.V.) Shade Canopies for Umbrella Shade Structure. Umbrella Metal Pole Supports.

Approximate shade dimensions 20' L x 20' W

**ICSA** Created: Tue 12 Sep 07:30 2023 South County Regional Park

Address: 670 Cooper St, Punta Gorda, Florida,

33950

No. Items: 13

Contact:

Company: CSA Consulting Group, LLC.

Phone: Email:



Created: Mon 18 Sep 2023


Group: Playground Shade & Structure A
GPS Lat/Lon: 26.93406, -82.03550
Cause of Damage: Wind/Windborne

**Debris** 

**Component Description:** 

High density polyethylene with ultra violet (U.V) shade canopy.

Approximate shade dimensions 50' L x 45' W



Created: Mon 18 Sep 2023

**Group:** Playground Shade & Structure **A** 

**GPS Lat/Lon:** 26.93406, -82.03550 **Cause of Damage:** Wind/Windborne

Debris

**Component Description:** 

High density polyethylene with ultra

violet (U.V) shade canopy.

CSA Created: Tue 12 Sep 07:30 2023

South County Regional Park

Address: 670 Cooper St, Punta Gorda, Florida,

33950

No. Items: 13

Contact:

**Company: CSA** Consulting Group, LLC.

Phone: Email:

(9)



**Created:** Tue 12 Sep 11:02 2023

**Group:** Soccer Field Shade & Structure A **GPS Lat/Lon:** 26.933314, -82.031727 **Cause of Damage:** Wind/Windborne


Debris

## **Component Description:**

Soccer Field Shade Structure (A) has experienced a series of damages, as the shade structure appeared to be warped out of its original shape.

Approximate shade dimensions 40' L x 40' W

(10)



**Created:** Tue 12 Sep 11:03 2023

Group: Soccer Field Shade & Structure A
GPS Lat/Lon: 26.933150, -82.031572
Cause of Damage: Wind/Windborne

Debris

# **Component Description:**

Soccer Field Shade Structure (A) has experienced a series of damages, as the shade structure appeared to be warped out of its original shape.

CSA Created: Tue 12 Sep 07:30 2023 Location: South County Regional Park

Address: 670 Cooper St, Punta Gorda, Florida,

33950

No. Items: 13 Contact:

Company: CSA Consulting Group, LLC.

Phone: Email:

Created: Tue 12 Sep 11:04 2023

Group: Soccer Field Shade & Structure A **GPS Lat/Lon:** 26.933150, -82.031572 Cause of Damage: Wind/Windborne

Debris

### **Component Description:**

Soccer Field Shade Structure (A) has experienced a series of damages, as the shade structure appeared to be warped out of its original shape. In this depiction, stress points are visually observable.



(12)



Created: Tue 12 Sep 11:04 2023

Group: Soccer Field Shade & Structure A GPS Lat/Lon: 26.933150, -82.031572 Wind/Windborne Cause of Damage:

Debris

#### **Component Description:**

Soccer Field Shade Structure (A) has experienced a series of damages, as the shade structure appeared to be warped out of its original shape. In this depiction, stress points are visually observable.

**CSA** Created: Tue 12 Sep 07:30 2023 South County Regional Park

Address: 670 Cooper St, Punta Gorda, Florida,

33950


No. Items: 13

Contact:

Company: CSA Consulting Group, LLC.

Phone: Email:

(13)



**Created:** Tue 12 Sep 11:04 2023

**Group:** Soccer Field Shade & Structure A **GPS Lat/Lon:** 26.933150, -82.031572 **Cause of Damage:** Wind/Windborne

Debris


## **Component Description:**

Soccer Field Shade Structure (A) has experienced a series of damages, as the shade structure appeared to be warped out of its original shape. In this depiction, stress points are visually observable.

Approximate shade dimensions 40' L x 40' W



Site Inspection Report for Charlotte County – Tringali Recreational Campus Florida Hurricane Ian (DR-4673-FL)







Title: Tringali Park

Address: 3460 N Access Rd, Englewood, FL 34224

No. Items: (16) Subject Photos

(1.)



Created: Thu 16 Nov 08:51 2023

Group: Playground Sail

Shade & Structure A

26.93505, -82.29203 GPS Lat/Lon:

**Cause of Damage:** High Winds

**Component Description:** 

**Company:** CSA Consulting Group

Overview Photo.

List of Damaged/Missing Components:

- (1) damaged North Sail Shade Fabric
- (1) missing South Sail Shade Fabric
- (2) Fasteners & Couplings
- (1) 12" Column Off Center
- (1) 20" Column Off Center
- (1) 10" Column Off Center
- Playground Structure (Reset) refer to Photo 10 for details.

Approximate shade dimensions 36' L x 31' W

(2.)



Created: Thu 16 Nov 09:09 2023

Group: Playground Sail

Shade & Structure A

GPS Lat/Lon: 26.93505, -82.29203

Cause of Damage: High Winds

**Component Description:** 

Deflection of the 12" dia. Column in question. Damaged fasteners and missing coupling.

Tringali Park

Address: 3460 N Access Rd, Englewood, FL 34224

No. Items: (16) Subject Photos

(3.)



Created: Thu 16 Nov 09:13 2023

Group: Playground Sail

Shade & Structure A 26.93505, -82.29203

Cause of Damage: High Winds

**Component Description:** 


Company: CSA Consulting Group

Refer to Photo (2).

**GPS Lat/Lon:** 

Diameter measurement.

(4.)



Created: Thu 16 Nov 09:10 2023

Group: Playground Sail

Shade & Structure A

GPS Lat/Lon: 26.93505, -82.29203

**Cause of Damage:** High Winds


**Component Description:** Refer to Photo (2).

Title: Tringali Park

Address: 3460 N Access Rd, Englewood, FL 34224

No. Items: (16) Subject Photos

(5.)



Created: Thu 16 Nov 09:11 2023

Group: Playground Sail

Shade & Structure A

26.93505, -82.29203 **GPS Lat/Lon:** 


Cause of Damage: High Winds

**Component Description:** 

Company: CSA Consulting Group

Refer to Photo (2).

(6.)



Created: Thu 16 Nov 09:14 2023

Group: Playground Sail

Shade & Structure A

GPS Lat/Lon: 26.93505, -82.29203

**Cause of Damage:** High Winds

**Component Description:** 

Refer to Photo (1).

Title: Tringali Park

Address: 3460 N Access Rd, Englewood, FL 34224

No. Items: (16) Subject Photos

(7.)



Created: Thu 16 Nov 09:09 2023

Group: Playground Sail

Shade & Structure A 26.93505, -82.29203

Cause of Damage: High Winds

**Component Description:** 

Company: CSA Consulting Group

Refer to Photo (1).

GPS Lat/Lon:

(8.)



Created: Thu 16 Nov 09:17 2023

Group: Playground Sail

Shade & Structure A

GPS Lat/Lon: 26.93505, -82.29203

**Cause of Damage:** High Winds

**Component Description:** Refer to Photo (1).

Tringali Park

Address: 3460 N Access Rd, Englewood, FL 34224

No. Items: (16) Subject Photos

(9.)



Created: Thu 16 Nov 09:21 2023

Group: Playground Sail

Shade & Structure A 26.93505, -82.29203

Cause of Damage: High Winds

**Component Description:** 

Company: CSA Consulting Group

Refer to Photo (1).

GPS Lat/Lon:

Measurement detail.

(10.)



Created: Thu 16 Nov 09:25 2023

Group: Playground Sail

Shade & Structure A

GPS Lat/Lon: 26.93505, -82.29203

**Cause of Damage:** High Winds

**Component Description:** 

Refer to Photo (1).

Deflection detail photo.

Title: Tringali Park

Address: 3460 N Access Rd, Englewood, FL 34224

No. Items: (16) Subject Photos

(11.)



Created: Thu 16 Nov 09:39 2023

Tennis Court 2 Group:

Offset Umbrella Shade & Structure A

GPS Lat/Lon: 26.93490, -82.29145

Cause of Damage: High Winds

**Component Description:** 

Company: CSA Consulting Group

Shade structure damaged. Hip rail detached.

**Damaged Components:** 

(1) 8' Hip Rail Arm

(1) Rail Sleeve

Approximate shade dimensions 10' L x 10' W

(12.)



Created: Thu 16 Nov 09:39 2023

**Group:** Tennis Court 2

> Offset Umbrella Shade & Structure A

GPS Lat/Lon: 26.93490, -82.29145

**Cause of Damage:** High Winds

**Component Description:** 

Refer to Photo (11). Displacement detail photo.

Title: Tringali Park

Address: 3460 N Access Rd, Englewood, FL 34224

No. Items: (16) Subject Photos



**Created:** Thu 16 Nov 09:47 2023

**Group:** Tennis Court 2

Offset Umbrella Shade & Structure A

**GPS Lat/Lon:** 26.93490, -82.29145

Cause of Damage: High Winds

**Component Description:** Refer to Photo (11).

**Company:** CSA Consulting Group

Detail of missing hip rail arm and damaged

sleeve.





**Created:** Thu 16 Nov 09:50 2023

**Group:** Tennis Court 3

Offset Umbrella

Shade & Structure B 26.93489, -82.29121

GPS Lat/Lon: 26.93489, -8 Cause of Damage: High Winds

**Component Description:** 

Shade structure damaged. Missing hip rail arm

with damage sleeve.

Damaged Components:

■ (1) 8' Hip Rail Arm

(1) Rail Sleeve

Approximate shade dimensions 10' L x 10' W

Title: Tringali Park

Address: 3460 N Access Rd, Englewood, FL 34224

No. Items: (16) Subject Photos

(15.)



**Created:** Thu 16 Nov 09:52 2023

**Group:** Tennis Court 3

Offset Umbrella Shade & Structure B

**GPS Lat/Lon:** 26.93489, -82.29121

Cause of Damage: High Winds

**Component Description:** 

Company: CSA Consulting Group

Refer to Photo (14). Displacement detail photo.

(16.)



**Created:** Thu 16 Nov 09:52 2023

**Group:** Tennis Court 3

Offset Umbrella Shade & Structure B

**GPS Lat/Lon:** 26.93489, -82.29121

Cause of Damage: High Winds

**Component Description:** Refer to Photo (14).

Measurement detail photo. 5.5" post.